

---

## PIC12F635 Rev. A Silicon/Data Sheet Errata

---

The PIC12F635 parts you have received conform functionally to the Device Data Sheet (DS41232D), except for the anomalies described below.

Microchip intends to address all issues listed here in future revisions of the **PIC12F635 silicon**.

### 1. Module: Resets (when WDT times out)

If the OPTION\_REG bits: PS<2:0> are changed from any other value to '000', multiple spurious Resets can occur when the WDT times out. These Resets can occur even when the PSA bit is clear, assigning the prescaler to the Timer0.

#### Work around

If a CLRWDI instruction is issued before the WDT times out and before the OPTION register PS<2:0> bits are modified, this problem is eliminated.

This issue was corrected in revision B silicon.

#### Date Codes that pertain to this issue:

All engineering and production devices.

### 2. Module: Data EEPROM Memory

The EEIF flag may be cleared inadvertently when performing operations on the PIR1 register simultaneously with the completion of a data EEPROM write. This condition occurs when the data EEPROM write timer completes at the same moment that the PIR1 register operation is executed. Register operations are those that have the PIR1 register as the destination and include, but are not limited to, BSF, BCF, ANDWF, IORWF and XORWF.

#### Work around

1. Avoid operations on the PIR1 register when writing to the data EEPROM memory.
2. Poll the WR bit (EECON1<1>) to determine when the write is complete.
3. Use a timer interrupt to catch any instances when the EEIF flag is inadvertently cleared. The timer interrupt should be set longer than 8 ms. If EEIF fails, then the timer interrupt occurs as a default time out. The WR and WRERR flags are checked as part of the timer interrupt service routine to verify the data EEPROM write success.

4. If periodic interrupts are occurring in addition to the EEIF interrupts, then use a secondary flag to sense write completion. The secondary flag is set whenever data EEPROM writes are active. A data EEPROM write completion is indicated when the secondary flag is set and the WR flag is clear.

### 3. Module: Wake-up Reset (WUR)

If a Wake-up Reset occurs when the Wake-up Reset (WURE) and Power-up Timer (PWRT) Configuration bits are enabled in revision A silicon, there will not be a 72 ms time delay as expected.

#### Work around

There is no work around in revision A silicon for this errata. However, this issue was corrected for revision B silicon. If a Wake-up Reset occurs when the Wake-up Reset and Power-up Timer Configuration bits are enabled in revision B silicon, there will be a nominal 72 ms time delay following a Wake-up Reset.

### 4. Module: Internal/External Clock Switch Over (IESO)

If a Wake-up Reset occurs when the Wake-up Reset (WURE) and Internal/External Clock Switch Over (IESO) Configuration bits are enabled in revision A silicon and there is no external clock applied to the chip when in the XT/HS configurations, the processor will hang on a Wake-up Reset.

#### Work around

There is no work around for revision A silicon for this errata. However, this issue was corrected for revision B silicon. If a Wake-up Reset occurs when the Wake-up Reset and Internal/External Clock Switch Over Configuration bits are enabled in revision B silicon and Wake-up Reset occurs, the chip will wake up and reset as expected.

# PIC12F635

---

## Clarifications/Corrections to the Data Sheet:

In the Device Data Sheet (DS41232D), the following clarifications and corrections should be noted.

None.

## Revision History

### Rev A Document (8/2004)

Issue 1 – When OPTION\_REG bits, PS<2:0>, are clear, multiple spurious Resets can occur when the WDT times out.

Added Clarification/Corrections to the Data Sheet, Issues 1, 2 and 3 (changed to 8-pin MF **saw singulated** packaging).

### Rev B Document (11/2004)

Added Module 2, “Data EEPROM Memory” for PIC12F635 silicon.

### Rev C Document (01/2005)

Revised Modules 1 and 2.

Deleted Clarifications/Corrections to the Data Sheet. Data Sheet has been updated.

### Rev D Document (07/2005)

Data Sheet Clarifications/Corrections Section: Added Module 1: New 4x4 DFN Package added.

### Rev E Document (10/2005)

Data Sheet Clarifications/Corrections Section: Replaced 8-Lead Plastic Dual Flat No Lead Package 4x4 (DFN).

### Rev F Document (02/2006)

Data Sheet Clarifications/Corrections section: Added Module 2: I/O Pins.

### Rev G Document (03/2006)

Data Sheet Clarifications/Corrections section: Added Module 3: Data EEPROM Memory; Added Module 4: Electrical Specifications.

### Rev H Document (06/14/06)

Added Module 3: “Wake-up Reset”, and Module 4: “Internal/External Clock Switch Over”.

### Rev J Document (04/2007)

Data Sheet Clarifications/Corrections section: Removed Data Sheet Modules per data sheet update.

---

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

**Trademarks**

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AmpLab, FilterLab, Linear Active Thermistor, Migratable Memory, MXDEV, MXLAB, PS logo, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, PICkit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rfLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2007, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

*Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona, Gresham, Oregon and Mountain View, California. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
== ISO/TS 16949:2002 ==**



---

---

## WORLDWIDE SALES AND SERVICE

---

---

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Kokomo**  
Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**  
Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**  
Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Fuzhou**  
Tel: 86-591-8750-3506  
Fax: 86-591-8750-3521

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Shunde**  
Tel: 86-757-2839-5507  
Fax: 86-757-2839-5571

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7250  
Fax: 86-29-8833-7256

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-4182-8400  
Fax: 91-80-4182-8422

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471-6166  
Fax: 81-45-471-6122

**Korea - Gumi**  
Tel: 82-54-473-4301  
Fax: 82-54-473-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Penang**  
Tel: 60-4-646-8870  
Fax: 60-4-646-5086

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-572-9526  
Fax: 886-3-572-6459

**Taiwan - Kaohsiung**  
Tel: 886-7-536-4818  
Fax: 886-7-536-4803

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820