



MICROCHIP PIC16F631/677/685/687/689/690

PIC16F631/677/685/687/689/690 Rev. A Silicon/Data Sheet Errata

The PIC16F631/677/685/687/689/690 parts you have received conform functionally to the Device Data Sheet (DS41262E), except for the anomalies described below.

All of the issues listed here will be addressed in future revisions of the PIC16F631/677/685/687/689/690 silicon.

1. Module: EUSART (PIC16F687/689/690 only)

1.1 WUE Bit is not clearing.

After a wake-up due to a Break character, the WUE bit is not automatically cleared.

Work around

Clear the WUE bit after waking up.

Fix

Rev. A5 Silicon and later revisions.

1.2 Auto-baud captures the incorrect baud rate after a break.

The SPBRGH:SPBRG registers are not being initialized correctly. If WUE and ABDEN are set at the same time and a Break character followed by a Sync character are received, then the calculated baud rate will be random.

Work around

Set WUE and wait for the wake-up to occur.

Clear SPBRGH:SPBRG after waking up with the break.

Set ABDEN to begin the auto-baud process.

Fix

Rev. A5 Silicon and later revisions.

1.3 Auto-baud calculates a baud rate value that is +2.

The SPBRGH:SPBRG are not initialized correctly when ABDEN is set. This causes the measured baud rate to be high by two counts.

Work around

Clearing the SPBRGH:SPBRG registers will correctly initialize the baud rate counter. After the auto-baud has been completed, the baud rate will now be +1. The firmware should now subtract 1 from the Baud Rate Generator to produce the correct baud rate.

Fix

Rev. A5 Silicon and later revisions.

1.4 Delay after auto-baud before transmit is allowed.

After the auto-baud Sync character has been received and the RCIF flag is set, there is approximately 17 ms of delay before the transmitter is enabled.

Work around

After the RCIF flag is set indicating the baud rate has been measured, read the SPBRG register and write the value back to SPBRG. This will terminate the delay, and enable the transmitter module.

Fix

Rev. A5 Silicon and later revisions.

1.5 Auto-baud sequence cannot be aborted in some cases.

If an auto-baud is started but no edges are received, there is no way to leave Auto-Baud mode.

Work around

Use the Watchdog Timer to reset the entire device.

Fix

Rev. A5 Silicon and later revisions.

PIC16F631/677/685/687/689/690

1.6 Clearing SPEN does not reset EUSART state machine correctly.

When SPEN is cleared, the entire EUSART is frozen. When SPEN is set, the EUSART resumes where it left off. This can cause some unexpected behavior.

Work around

To reset the EUSART, toggle TXEN and CREN after clearing SPEN. This will reset the transmit and receive state machines.

Fix

Rev. A5 Silicon and later revisions.

1.7 Extra character transmitted after auto-baud.

If TXEN is high when ABDEN is set, it will be cleared as soon as the auto-baud process begins, and reset as soon as the auto-baud process completes. When TXEN is reset, the character in the transmit queue will be transmitted.

Work around

Before starting auto-baud, clear TXEN. This will reset the transmit state machine correctly. After the auto-baud is complete and the firmware has brought TXEN high, no character will be transmitted.

Fix

Rev. A5 Silicon and later revisions.

2. Module: SSP (PIC16F687/689/690 only)

2.1 SSP module does not recognize first Start bit received.

In any of the I²C™ modes, the SSP module will fail to recognize the first Start bit received after a transition from module disable to module enable. Subsequent Stop bits and Start bits are detected properly.

Work around

Enable the SSP module in SSPMSK Access mode before changing the mode to the desired I²C operation.

EXAMPLE 1: CODE EXAMPLE

```
MOVLW B'00111001' ;Module enable, clock
MOVWF SSPCON        ;enable, SSPMSK access.
                    ;Optionally load
                    ;address mask value
                    ;into SSPMSK register.
MOVLW B'00110110' ;Module enable, clock
MOVWF SSPCON        ;enable, 7-bit address
                    ;I2C slave.
```

Fix

Rev. A6 Silicon and later revisions.

2.2 Under certain conditions, the SSPIF flag sets on reception of the first byte.

When all of the following conditions are met:

- The module is configured as a SPI slave
- CKP = 1
- CKE = 1
- Multiple bytes are sent with the \overline{SS} line remaining low between bytes

The SSPIF flag will only be set on reception of the first byte and the following bytes will not be correctly received.

Work around

- Toggle the \overline{SS} line between bytes

or

- On reception of the first byte modify the SSPM bits in the SSPCON register to configure the module as a SPI slave with \overline{SS} pin disabled. Then restore the SSPM bits to the configuration for SPI slave with \overline{SS} pin enabled. The module is then ready for reception of the following byte.

Fix

None.

3. Module: ECCP with Auto-Shutdown (Silicon Rev. A4 and previous revisions) (PIC16F685 and PIC16F690 only)

The PIC16F631/677/685/687/689/690 Rev. A4 silicon for the ECCP auto-shutdown is connected to the C1IF and C2IF flags. See Figures 8-2 and 8-3 on the following page.

The auto-shutdown connection (Rev. A4 and previous) to C1IF and C2IF causes the auto-shutdown to incorrectly operate synchronously. Additionally, reads of CMxCON0 will incorrectly clear an auto-shutdown event.

Work around

Rev. A4 Silicon and previous revisions.


- 1) Poll the CxOUT bit until it is low.
- 2) Read CMxCON0 to precondition CxIF.
- 3) If CMxCON0 is read while CxOUT is changing, repeat steps 1 and 2.

Fix

Rev. A5 Silicon and later revisions.

The Silicon Rev. A5 (now shipping) and later revision devices have moved the auto-shutdown connection from CxIF to CxOUT. This will eliminate the synchronous shutdown and simplify the use of the comparator for a shutdown event. Figure 1 shows the function of auto-shutdown before and after the device revision.

FIGURE 8-2: COMPARATOR C1 SIMPLIFIED BLOCK DIAGRAM



PIC16F631/677/685/687/689/690

FIGURE 8-3: COMPARATOR C2 SIMPLIFIED BLOCK DIAGRAM





FIGURE 1: SILICON REVISION A4 AND PREVIOUS VS. REVISION A5



4. Module: Analog-To-Digital Converter (ADC) Module (PIC16F685/687/689/690 Only)

Selecting the VP6 reference as the analog input source (CHS<3:0> = 1101) for the ADC conversion after sampling another analog channel with input voltages approximately greater than 1.2V can temporarily disturb the HFINTOSC oscillator.

Note: This only occurs when selecting the VP6 reference ADC channel using the CHS<3:0> bits in the ADCON0 register and NOT during the start of an actual ADC conversion using the GO/DONE bit in the ADCON0 register.

Work around

Select an ADC channel with input voltages lower than 1.2V prior to selecting the VP6 reference voltage input. Any analog channel can be used, even if that channel is configured as a digital I/O (configured as an output) that is driving the output pin low. An alternative is to configure the CVREF module to output a voltage less than 1.2V and then selecting that analog channel CHS<3:0> = 1100 as the analog input source.

EXAMPLE 2: AVOID DISTURBING THE HFINTOSC OSCILLATOR

```
BANKSEL    ADCON0    ;
MOVLW     B'XX110001' ;Select ADC
MOVWF     ADCON0     ;Channel CVREF
MOVLW     B'XX110101' ;Select ADC
MOVWF     ADCON0     ;Channel VP6
```

Silicon Fix

None.

5. Module: LP/Timer1 Oscillator Operation Below 25°C

At temperatures below 25°C, the shared LP and Timer1 external 32 kHz Oscillator module may have reduced oscillator peak-to-peak voltage with decreasing temperature.

This can cause irregular Timer1 overflow or instruction execution and in extreme cases, oscillations may stop.

The same issue may also prevent the external 32 kHz oscillator from starting up at low temperatures.

Work around

Adding an external 1 MOhm pull-up resistor on OSC2 allows the oscillator to start and run successfully over its operating temperature range.

Silicon Fix

None.

6. Module: SSP (PIC16F687/689/690)

When all of the following conditions are met:

1. The module is configured as a SPI slave
2. CKP = 1
3. CKE = 1
4. Multiple bytes are sent with the SS line remaining low between bytes

The SSPIF flag will only be set on reception of the first byte and the following bytes will not be correctly received.

Work around

- Toggle the SS line between bytes

or

- On reception of the first byte modify the SSPM0 bit in the SSPCON register to configure the module as a SPI slave with SS pin disabled. Then restore the SSPM0 bit to the configuration for SPI slave with SS pin enabled. The module is then ready for reception of the following byte.

```
bsf SSPCON, SSPM0
```

```
bcf SSPCON, SSPM0
```

Silicon Fix

None.

PIC16F631/677/685/687/689/690

Clarifications/Corrections to the Data Sheet:

In the Device Data Sheet (DS41262E), the following clarifications and corrections should be noted.

None.

PIC16F631/677/685/687/689/690

REVISION HISTORY

Rev A Document (7/2005)

Original release of this document.

Clarifications/Corrections to the Data Sheet:

Added Modules 1 through 7:

Module 1: Device VDD Range

Module 2: 4x4 QFN Package Marking

Module 3: Table 1-1: Pinout Description – PIC16F685

Module 4: Register 10-5: EECON1

Module 5: Table 11-2: Registers Associated with
Capture, Compare and Timer1

Module 6: Section 12.0 EUSART

Module 7: Section 14.2.2 MCLR

Rev B Document (8/2005)

Silicon Section:

Added Module 1: EUSART (PIC16F687/689/690 only).

Clarifications/Corrections to the Data Sheet:

Added Modules 8 and 9:

Module 8: SSP Module Overview

Module 9: Electrical Specifications.

Rev C Document (11/2005)

Silicon Section:

Added Module 2: SSP (PIC16F687/689/690 only)

Rev D Document (01/2006)

Clarifications/Corrections to the Data Sheet:

Replaced the 20-Lead QFN package diagram in
Module 2: 4x4 QFN Package Marking.

Rev E Document (7/2006)

Data Sheet Clarifications/Corrections Section:
Removed Items 1 through 9, which have been
incorporated into the data sheet. Added Item 1, 20-pin
QFN Pin Diagram Title change.

Rev F Document (11/2006)

Data Sheet Clarifications/Corrections Section: Added
Item 2, Product Identification System, Examples
change.

Added Module 3: ECCP with Auto-Shutdown (Silicon
Rev. B2). Updated Module1: EUSART (PIC16F687/
689/690 only) and Module2: SSP (PIC16F687/689/690
only) with Fix information.

Rev G Document (01/2007)

Removed Rev. A6 reference from Module 2 (SSP).

Data Sheet Clarifications/Corrections Section: Added
Module 3, Comparator and Voltage Reference Modules
Associated Registers, removed REFCON register
reference. Added Module 4: DC Characteristics, Table
17.3, revised Max values.

Rev H Document (07/2007)

Added Module 4: Analog-to-Digital Converter (ADC)
Module. Module 2: Added Fix.

Rev J Document (09/2008)

Added Module 2.2: Under certain conditions, the
SSPIF flag sets on reception of the first byte (under
new 2. SSP (PIC16F687/689/690 only)), while
changing Module 2. to 2.1. Revised Module 5: LP/
Timer1 Oscillator Operations Below 25°C. Added
Module 6: SSP.

Clarifications/Corrections to the Data Sheet:

Removed Modules 1 through 4, which have been
included in the latest data sheet revision.

PIC16F631/677/685/687/689/690

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, rfPIC, SmartShunt and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC³² logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rfLAB, Select Mode, Total Endurance, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2008, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office

2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta

Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo

Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara

Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto

Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office

Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney

Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing

Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu

Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Hong Kong SAR

Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing

Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao

Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai

Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang

Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen

Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan

Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xiamen

Tel: 86-592-2388138
Fax: 86-592-2388130

China - Xian

Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Zhuhai

Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore

Tel: 91-80-4182-8400
Fax: 91-80-4182-8422

India - New Delhi

Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune

Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama

Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Daegu

Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul

Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur

Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang

Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila

Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore

Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu

Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung

Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei

Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok

Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels

Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen

Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris

Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich

Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan

Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen

Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid

Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham

Tel: 44-118-921-5869
Fax: 44-118-921-5820