

dsPIC33F Engineering Samples Rev. A0/A1 Silicon Errata

dsPIC33FJXXXGPXXX, dsPIC33FJXXXMCXXX (Rev. A0/A1) Silicon Errata

The dsPIC33F Engineering Samples (Rev. A0/A1) you received were found to conform to the specifications and functionality described in the following documents:

- DS70165 – “dsPIC33F Family Data Sheet”
- DS70157 – “dsPIC30F/33F Programmer’s Reference Manual”
- DS70046 – “dsPIC30F Family Reference Manual”

The exceptions to the specifications in the documents listed above are described in this section. The specific devices for which these exceptions are described are listed below:

- dsPIC33FJ128GP706-PT ES
- dsPIC33FJ128GP708-PT ES
- dsPIC33FJ256GP506-PT ES
- dsPIC33FJ256GP710-PF ES
- dsPIC33FJ256GP710-PT ES
- dsPIC33FJ128MC706-PT ES
- dsPIC33FJ128MC708-PT ES
- dsPIC33FJ256MC710-PF ES
- dsPIC33FJ256MC710-PT ES

dsPIC33F Rev. A0/A1 silicon is identified by performing a “Reset and Connect” operation to the device using MPLAB® ICD 2 with MPLAB IDE v7.31.01 or later. The output window will show either:

1. A successful connection to the device specified in Configure>Select Device
2. Warning message ICD Warn0020: Invalid target device id. If this message is received, consult the “dsPIC33F Flash Programming Specification” (DS70152) to verify the device ID. This device mismatch will be fixed in future revisions of MPLAB IDE.

The errata described in this section will be addressed in future revisions of silicon.

Silicon Errata Summary

The following list summarizes the errata described in further detail through the remainder of this document:

1. SPI with 1:1 Prescaler
The SPI modules do not function correctly when the SPI clock prescale ratio is set to 1:1.
2. SPI Master Reception for Bit Rates above 8 Mbps
SPI Master reception does not function correctly at bit rates higher than 8 Mbps, if the data is sampled at the middle of the serial clock period.
3. Analog-to-Digital Converter (ADC) with Sample/Hold CH3
Sample/Hold amplifier CH3 does not function correctly for the Analog-to-Digital Converter modules.
4. LATC and LATD Reads
The LATC and LATD register reads do not function.
5. DMA Single-Shot Mode
The Direct Memory Access Single-Shot mode does not function correctly.
6. Windowed Watchdog Timer
When the Windowed WDT option is enabled and the WDT is disabled, a WDT time out will occur.
7. Timer3 as A/D Conversion Trigger Source
Timer2 and Timer3, when configured as a single 32-bit timer, may not initiate an A/D conversion if the PR3 register is set to '0' and Timer3 is selected as the A/D conversion trigger source.
8. UART Auto-Baud
The UART FIFO will be loaded with incorrect data if the UxBRG register is not initialized to a specific value.
9. Doze Mode
When Doze mode is enabled, any writes to a peripheral SFR can cause other updates to that register to cease to function for the duration of the current CPU clock cycle.

dsPIC33F ENGINEERING SAMPLES

10. 12-bit ADC Module

For this revision of silicon, the 12-bit ADC module INL and DNL, conversion speed and signal acquisition time parameters are not within the published data sheet specifications.

11. 10-bit ADC Module

For this revision of silicon, the 10-bit ADC module INL, DNL and signal acquisition time parameters are not within the published data sheet specifications.

12. DMA Module: Interaction with EXCH Instruction

The EXCH instruction does not execute correctly when one of the operands contains a value equal to the address of the DMAC SFRs.

13. DISI Instruction

The DISI instruction will not disable interrupts if a DISI instruction is executed in the same instruction cycle that the DISI counter decrements to zero.

14. Motor Control PWM

There is a glitch in the PWMxL signal in Single-Shot mode with complementary output. Another glitch occurs when resuming from a Fault condition in Free-Running mode with complementary output.

15. JTAG Programming

JTAG programming will not work in silicon revision A0/A1.

16. Internal FRC Oscillator

The internal FRC oscillator is not calibrated in silicon revision A0/A1.

17. ECAN™ Loopback Mode

The ECAN module (ECAN1 or ECAN2) does not function correctly in Loopback mode.

18. Clock Switch From Fail-Safe Clock Source

Once a clock fail interrupt has occurred, the clock source cannot be switched from the fail-safe clock source.

19. I²C™ Module

The I²C module does not wake-up from Sleep when it detects bus activity.

The following sections will describe the errata and work around to these errata, where they may apply.

dsPIC33F ENGINEERING SAMPLES

1. Module: SPI with 1:1 Prescaler

The SPI1 and SPI2 modules do not generate any serial clock signals and, therefore, do not function correctly for the following values of the PPRE<1:0> (SPIxCON1<1:0>) and the SPRE<2:0> (SPIxCON1<4:2>) bits:

- PPRE = 11, SPRE = 111

Work around

Users may set up the SPI module with any prescale ratio other than 1:1.

2. Module: SPI Master Reception for Bit Rates above 8 Mbps

Master mode receptions using the SPI1 and SPI2 module do not function correctly for bit rates above 8 Mbps if the Master has the SMP bit (SPIxCON1<9>) cleared (Master samples data at the middle of the serial clock period).

In this case, the data transmitted by the Slave is received shifted right by one bit by the Master. For example, if the data transmitted by the Slave was 0xAAAA, the data received by the Master would be 0x5555 (0xAAAA shifted right by one bit).

Work around

Users may set up the SPI module so that the bit rate is 8 Mbps or lower.

Alternatively, the bit rate can be configured higher than 8 Mbps, but the SMP bit (SPIxCON1<9>) of the SPI Master must be set (Master samples data at the end of the serial clock period).

3. Module: ADC with Sample/Hold CH3

The Sample/Hold amplifier CH3 does not function correctly when used with the Analog-to-Digital Converter (ADC) modules. The corresponding conversion result is always read as 0x0000.

Work around

Do not use the Sample/Hold amplifier CH3 with the ADC1 or ADC2 module. You may use CH0, CH1 and CH2.

4. Module: LATC and LATD Reads

The LATC and LATD register reads do not function. Performing a read or read-modify-write operation on the LATC register or the LATD register will not function.

Do not perform read or read-modify-write operations on the LATC and LATD registers. Inspect the disassembly listing of any user application software that may be accessing the LATC or LATD register, to ensure that read or read-modify-write operations are not being performed on these registers.

To verify the contents of the LATC register, perform the following steps:

- Write to LATC
- Make a PORTC pin an output
- Read the PORTC register

The same steps can be performed to verify the contents of the LATD register.

Note: The Port pin state, and therefore the read value, depends on the load attached to the Port pin.

5. Module: DMA Single-Shot Mode

The DMA Single-Shot mode does not function correctly for more than one block transfer. After one block transfer, the DMA channel becomes unusable until a device reset occurs.

Work around

If more than one DMA data block transfer is required during the entire program execution, the user application may set up the required DMA channel to operate in Continuous mode, and disable the DMA channel every time the corresponding DMA interrupt has occurred.

However, if only one DMA data block transfer is required for a particular DMA channel during the entire program execution, Single-Shot mode may be used.

6. Module: Watchdog Timer

When the WDT is disabled and the WDT Window is enabled, a WDT time out will occur and cause the device to reset unexpectedly. The WDT is disabled by clearing the FWDTEN bit (FWDTC<7>). The WDT Window feature is enabled by clearing the WINDIS bit (FWDTC<6>).

Work around

In order to prevent an unexpected WDT time out when the WDT is disabled, disable the WDT Window feature by setting the WINDIS bit (FWDTC<6>).

dsPIC33F ENGINEERING SAMPLES

7. Module: ADC with Timer as Conversion Trigger Source

The ADC module can be configured so that Timer3 ends ADC sampling and starts the conversion (ADCON<7:5> = 010). PR3, the Timer3 period register, is loaded with a value that is compared to TMR3. In the ADC mode described, when TMR3 is equal to PR3, an A/D conversion is initiated.

Timer3 can also initiate an A/D conversion when Timer2 and Timer3 are configured as a single 32-bit timer. However, when Timer2 and Timer3 are configured as a single 32-bit timer, an A/D conversion may not be initiated if the PR3 register is set to '0'.

Work around

When Timer3 is selected as the trigger for initiating an A/D conversion (i.e. ADCON<7:5> = 010), make sure that PR3 is non-zero.

8. Module: UART Auto-Baud

When auto-baud is enabled (UxMODE<5> is set), the UART FIFO will be loaded with incorrect data unless the UxBRG register is initialized to 0xFFFF.

Work around

Initialize the UxBRG register to 0xFFFF anytime auto-baud is enabled.

9. Module: Oscillator: Doze Mode

Enabling Doze mode slows down the CPU but allows peripherals to run at full speed. When the CPU clock is slowed down by enabling Doze mode (CLKDIV<11> = 1), any writes to a peripheral SFR can cause other updates to that register to cease to function for the duration of the current CPU clock cycle. This is only an issue if the CPU attempts to write to the same register as a peripheral while in Doze mode.

For instance, if the ADC module is active and Doze mode is enabled, the main program should avoid writing to ADCCONx registers because these registers are being used by the ADC module. If the CPU does make writes before the ADC module does, then any attempts by the ADC module to write to these registers will fail.

Work around

In Doze mode, avoid writing code that will modify SFRs which may be written to by enabled peripherals.

10. Module: 12-bit ADC

1. When the ADC module is configured for 12-bit operation, the ADC INL is $>\pm 2$ LSBs and DNL is $>\pm 1$ LSB.
2. The conversion speed is limited to 400 Ksps and requires a minimum signal acquisition time of 266 nS.

Work around

Implement the ADC module as either a 10 or 11-bit A/D Converter.

1. When used as a 10-bit ADC, the INL is $\leq \pm 2$ LSBs, and DNL is $\leq \pm 1$ LSB with no missing codes.
2. When used as an 11-bit ADC, the INL is $\leq \pm 2$ LSBs and DNL is ± 1 LSB with missing codes at each 2^7 power boundary. ADC monotonicity is still realized if the missing codes are ignored.

Future versions of the silicon will support full 12-bit operation with $\leq \pm 2$ LSBs INL and $\leq \pm 1$ LSB DNL, a 500 Ksps conversion rate and a 133 nS signal acquisition time.

11. Module: 10-bit ADC

The ADC module INL is $>\pm 2$ LSBs and DNL is $>\pm 1$ LSB.

Work around

None. Future versions of the silicon will support $\leq \pm 2$ LSBs INL and $\leq \pm 1$ LSB DNL specifications, and a 70 nS signal acquisition time.

12. Module: DMA Module: Interaction with EXCH Instruction

The EXCH instruction does not execute correctly when either of the two operands is numerically equal to the address of any of the DMAC SFRs for this revision of silicon.

Work around

If writing source code in assembly, the recommended fix is to replace:

```
EXCH Wsource, Wdestination  
  
with:  
  
PUSH Wdestination  
MOV Wsource, Wdestination  
POP Wsource
```

If using the MPLAB C30 C compiler, check the disassembly listing ([View>Disassembly Listing](#)) for the EXCH instruction. If used, make sure the operands are not equivalent to the DMA SFRs' addresses.

dsPIC33F ENGINEERING SAMPLES

13. Module: DISI Instruction

When a user executes a DISI #7, for example, this will disable interrupts for 7 + 1 cycles (7 + the DISI instruction itself). In this case, the DISI instruction uses a counter which counts down from 7 to 0. The counter is loaded with 7 at the end of the DISI instruction.

If the user code executes another DISI on the instruction cycle where the DISI counter has become zero, the new DISI count is loaded, but the DISI state machine does not properly re-engage and continue to disable interrupts. At this point, all interrupts are enabled. The next time the user code executes a DISI instruction, the feature will act normally and block interrupts.

In summary, it is only when a DISI execution is coincident with the current DISI count = 0, that the issue occurs. Executing a DISI instruction before the DISI counter reaches zero will not produce this error. In this case, the DISI counter is loaded with the new value, and interrupts remain disabled until the counter becomes zero.

Work around

When executing multiple DISI instructions within the source code, make sure that subsequent DISI instructions have at least one instruction cycle between the time that the DISI counter decrements to zero and the next DISI instruction. Alternatively, make sure that subsequent DISI instructions are called before the DISI counter decrements to zero.

14. Module: Motor Control PWM

Devices in the motor control family have a glitch in the PWMxL signal under certain conditions. The glitch is a brief high pulse during the low portion of the duty cycle. This error occurs when the module is configured in Single-Shot mode (PTMOD<1:0> = 01) with complementary output. It also occurs when resuming from a Fault condition in Free-Running mode (PTMOD<1:0> = 00) with complementary output.

Work around

None.

15. Module: JTAG Programming

JTAG programming does not work in silicon revision A0/A1.

Work around

None.

16. Module: Internal FRC Oscillator

The internal FRC oscillator is not calibrated on silicon revision A0/A1.

Work around

The user can calibrate the internal oscillator manually by modifying the OSCTUN bits. This is done by using a waveform generator or other external source to generate a square wave of known frequency on one of the input capture pins. Configure the corresponding Input Capture module to measure the square wave period. Calculate the value that the input capture module should generate based on a nominal internal FRC oscillator frequency of 7.37 MHz. Adjust the OSCTUN bits until the measured input capture value matches the calculated value.

17. Module: ECAN Loopback Mode

The ECAN module (ECAN1 or ECAN2) does not function correctly in Loopback mode.

Work around

Do not use Loopback mode.

18. Module: Oscillator Configuration Block

If the fail-safe clock monitoring function is enabled, during a failure of the external oscillator, the device will automatically switch to the internal FRC oscillator. A clock failure trap event is also generated. In revision A0/A1 parts, once this interrupt occurs, the clock source cannot be switched from the internal FRC oscillator.

Work around

The user must issue a Reset before attempting to change clock sources after a clock fail event.

19. Module: I²C

The I²C module does not wake-up from Sleep when it detects bus activity.

Work around

None.

dsPIC33F ENGINEERING SAMPLES

APPENDIX A: REVISION HISTORY

Revision A (2/2006)

- First release of the document.

Revision B (5/2006)

- Added silicon issues 6 (Windowed Watchdog Timer, 7 (Timer3 as A/D Conversion Trigger Source), 8 (UART Auto-Baud), 9 (Doze Mode), 10 (12-bit ADC), 11 (10-bit ADC), 12 (DMA Module: Interaction with EXCH Instruction), 13 (DISI Instruction), 14 (Motor Control PWM), 15 (JTAG Programming), 16 (Internal FRC Oscillator), 17 (ECAN Loopback Mode), 18 (Clock Switch from Fail-Safe Clock Source) and 19 (I²C Module).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELoq, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

Amplab, FilterLab, Migratable Memory, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Linear Active Thermistor, Mindi, MiWi, MPASM, MPLIB, MPLINK, PICKit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2006, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona, Gresham, Oregon and Mountain View, California. The Company's quality system processes and procedures are for its PICmicro® 8-bit MCUs, KEELoq® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta

Alpharetta, GA
Tel: 770-640-0034
Fax: 770-640-0307

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo

Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

San Jose

Mountain View, CA
Tel: 650-215-1444
Fax: 650-961-0286

Toronto

Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8676-6200
Fax: 86-28-8676-6599

China - Fuzhou
Tel: 86-591-8750-3506
Fax: 86-591-8750-3521

China - Hong Kong SAR

Tel: 852-2401-1200
Fax: 852-2401-3431

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Shunde
Tel: 86-757-2839-5507
Fax: 86-757-2839-5571

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7250
Fax: 86-29-8833-7256

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-4182-8400
Fax: 91-80-4182-8422

India - New Delhi
Tel: 91-11-5160-8631
Fax: 91-11-5160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Gumi
Tel: 82-54-473-4301
Fax: 82-54-473-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Penang
Tel: 60-4-646-8870
Fax: 60-4-646-5086

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-399
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820