

- A. TRIM CABLE AS SHOWN
- B. INSERT CABLE W/ CENTER PRESSING INTO RECEPTACLE
- C. SOLDER OUTER CONDUCTOR TO BODY
- D. APPLY HEAT SHRINK AS REQUIRED

REV
B