



Figure 1 is a technical drawing showing the dimensions of the connector. The drawing includes a side view of the connector assembly. Key dimensions and labels are as follows:

- 0.3**: Vertical dimension indicating the offset of the connector's top surface from the mounting axis.
- ROW B AXIS**: A horizontal reference line passing through the center of the connector.
- MOUNTING AXIS OF THE CONNECTOR**: A horizontal reference line below the ROW B AXIS.
- 12.4/14.2 AFTER MATING**: Horizontal dimension indicating the distance from the mounting axis to the center of the connector after mating.
- 3.55** and **3.85**: Vertical dimensions indicating the distances from the mounting axis to the top and bottom surfaces of the connector, respectively.

[illegible]

PDM: Rev:D **STATUS: Released** Printed: Oct 30, 2007