HITACHI SEMICONDUCTOR TECHNICAL UPDATE

DATE		ember 2001		No.	TN-SH7-390A/E
ТНЕМЕ	Correction of errors on SH7622 hardware manual				
CLASSIFICATION	Spec. change				
PRODUCT NAME	HD6417622				
REFERENCE DOCUMENTS	SH7622 Hardware manual Rev2.0			Effective Date Eternity From	
Below is additional information to SH7622 hardware manual Rev 2.0.					
1. Correction of errors on '1.3.2 Pin Functions'					
1.1 Pin Functions (Page:11)					
111 1 111 1 111		TBP-208A	Pin Name		
[Error]		R4	D2		
[Correction]		P4	D2		
1.2 P. F. a. C. v. N. v. a. (D. v. 17)					
1.2 Pin Functions Notes (Page:17)					
[Error]		except for the No. 5(FP-2	16) and No.4(Fl	P-208C),	, which should be left open.
[Cor		1 except for the No. 5(FP-216), No.4(FP-208C) and No.C2(TBP-208A), which should be left open.			
	"	men should be left open.			